

**From:** [Azhar, Wardah](#)  
**To:** [Zhen, Davis](#); [Sheldrake, Sean](#)  
**Cc:** [Scott Coffey](#); [younghs@cdmsmith.com](mailto:younghs@cdmsmith.com)  
**Subject:** Re: Subsurface coring 7/31  
**Date:** Tuesday, July 31, 2018 2:55:22 PM  
**Attachments:** [image1.jpeg](#)  
[image1.jpeg](#)  
[image2.jpeg](#)

---

Core being cut in half for storage



Core in PVC pipe on ice



On Jul 31, 2018, at 12:24 PM, Azhar, Wardah <[azharw@cdmsmith.com](mailto:azharw@cdmsmith.com)> wrote:

Water draining out of holes drilled at the top of core tube.



Core being cut in half for storage, sediment can be seen seeping out.  
<image1.jpeg>

On Jul 31, 2018, at 9:17 AM, Azhar, Wardah <[azharw@cdmsmith.com](mailto:azharw@cdmsmith.com)> wrote:

Core tube being inserted at first location in the International slip, next to pier.

<IMG\_5008.JPG>

Wardah